

Job No (Operational use only)	Street	Tree Location	Total Trees Considered on Street at this time	Tree Species	Primary reason for tree being identified for replacement	Date(s) of ITP Site Work	Streetside Technical or Observed Issues the ITP which is being to SCC's attention	House hold on Street	Reason for ITP	Response %	Number of Respondents Disagreeing with Proposal	% of Respondents Disagreeing with Proposal	% of Households Disagreeing with Proposal	ITP Tree Category	Summary of ITP Advice (Note where relevant, this is due to copying to avoid any errors from auto-type from a letter which groups trees in a format which deals with trees individually)	Actions required to consider the advice	Streets Ahead Response	Response Prepared By	Decision on Further Action	Decision Made by	Amey's Comments	Streets Ahead Proposal	Streets Ahead Reasons for Proposal	Response Prepared By	Final Decision	Reasons for Decision	Final Decision Made By (Print name)	Final Decision Made By (Designation)	Final Decision Made By (Signature)	Date of Final Decision	Other Parties Involved in recommendation following ITP		
1202328	Edgemoor Road	Opp 28	1	Tilia x europaea	Rooting into c/w - no way to repair with tree intact, kerbs absent	24/06/16 and 11/07/16	None	25	8	32.00%	6	75.00%	24.00%	Tree which is healthy	The tree, outside number 28, is in good condition and has good life expectancy. We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of this tree. The tree is causing some disruption to the pavement and displacement of kerbs. We believe engineering solutions, including 1, 2 and 7, would enable this tree to be retained. We therefore advise the Council to consider this.	Assess site to verify we agree with options given. Request Amey to design if required	Replace tree as planned	SCC - Environmental Maintenance Technical Officer	N/A	N/A	This tree is rooting into the carriageway and the kerb line is missing	Engineering assessment as to whether the advice can be implemented within the Council's published guidance	Engineering assessment has shown that the ITP advice cannot be implemented within the Council's published guidance and design guidelines	SCC - Environmental Maintenance Technical Officer	Replace tree as planned	All advice considered	Simon Green	Executive Director (P/As)		03/02/2017	N/A		
1202338	Opposite 70		2	Platanus x hispanica	Herbaceous absent and f/w obstructed, cannot repair or specification without extensive root damage	24/06/16 and 11/07/16	We noted that the tree has been in an short section of the street.	108	13	12.04%	8	61.54%	7.41%	Trees which are healthy	The tree trees are in good condition and have good life expectancy. We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of this tree. The tree is causing some disruption to the pavement and displacement of kerbs. We believe engineering solutions, including 1, 2 and 7, would enable this tree to be retained. We therefore advise the Council to consider this.	Inspect this tree and see why the damage no longer appears to be a problem	CCP teams have successfully carried out repair and temporary works to the kerbs and ramps on site, this tree no longer requires removal	SCC - Environmental Maintenance Technical Officer	N/A	N/A	CCP teams have successfully carried out repair and temporary works to the kerbs and ramps on site, this tree no longer requires removal	Cancel full job as engineering solutions have been successfully applied	Engineering solutions have been successfully applied	SCC - Environmental Maintenance Technical Officer	Retain Tree	Trees retained by engineering solutions	Simon Green	Executive Director (P/As)		03/02/2017	N/A		
1202330	Sanford Grove Road	Opp 82 (Opp 75)		Platanus x hispanica	Extensive herb damage, growing within c/w - impossible to adequately repair without tree removal	24/06/16 and 11/07/16								Trees which are healthy	The tree outside 82 (opposite 75) is causing significant damage to the pavement, kerbs and displacement of kerbs. We believe engineering solutions, including 1, 2 and 7, would justify the removal and replacement of this tree.	None Required	Replace tree as planned	SCC - Environmental Maintenance Engineer	N/A	N/A	N/A	Continue with tree replacement as planned.	ITP, SCC and Amey in agreement.	SCC - Environmental Maintenance Engineer	Replace tree as planned	All advice considered	Simon Green	Executive Director (P/As)		03/02/2017	N/A		
1202403	Opp 18			Prunus serotina	TR: Falling - Dead									Trees which are dead	The tree outside number 18 is dead. We advise that this tree should be removed and replaced.	None Required	Replace tree as planned	SCC - Environmental Maintenance	N/A	N/A	N/A	Continue with tree replacement as planned.	ITP, SCC and Amey in agreement.	SCC - Environmental Maintenance	Replace tree as planned	All advice considered	Simon Green	Executive Director (P/As)		03/02/2017	N/A		
1202405	Robertson Drive	Opp 17-19	2	Acer platanoides	TR: Falling - Extensive rooting within c/w, will be severed upon road surfacing - unable to repair without root/tree removal	01/07/2016	None	22	2	9.09%	2	100.00%	9.09%	Trees which are healthy	The tree outside number 17-19 is a maple and is in good condition. We advise that there is no arboricultural need to remove this tree. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of this tree. We believe engineering solutions, including 1, 2 and 7, would enable this tree to be retained. We therefore advise the Council to consider this.	Inspect to see if solution could be effective and practicable	Roots should not be pruned within the root protection zone as this can be pruned, however it is preferable that this is assessed on a case by case basis by an experienced arboricultural practitioner. Root pruning can have an adverse effect on the stability or future vitality of the tree.	SCC - Environmental Maintenance Engineer	N/A	N/A	Root pruning is not advisable due to the detrimental effect it will have on both the tree's structural stability as well as disease susceptibility.	Continue with tree replacement as planned.	ITP, SCC and Amey in agreement.	SCC - Environmental Maintenance Engineer	Replace tree as planned	All advice considered	Simon Green	Executive Director (P/As)		03/02/2017	N/A		
1202407	Opp 41			Prunus x hispanica	TR: Falling - Significant lateral rooting at surface - cannot surface adequately	01/07/2016	None	12	7	58.33%	7	100.00%	58.33%	Trees which are diseased or damaged	The tree outside number 41 has reduced vitality, insect wounds and infection. The tree is also causing damage to the pavement. We advise that this tree should be removed and replaced.	Check that Amey were aware of the reduced vitality	We need to ensure that all are agreed on the date of each tree.	SCC - Environmental Maintenance Engineer	Continue with check	SCC - (Head of Highway Maintenance)	N/A	N/A	This is a cherry in fair overall condition but with symptoms of Pseudomonas syringae PV morsum (Black hole of cherry) and potentially Mytilina cerasi (Cherry bark beetle) which are common on Prunus sp. I would agree that the tree for these reasons, the foliage damage just tips the balance in my view towards removal.	Continue with tree replacement as planned.	ITP, SCC and Amey in agreement.	SCC - Environmental Maintenance Engineer	Replace tree as planned	All advice considered	Simon Green	Executive Director (P/As)		03/02/2017	Amey (Pre-site Technician)
1202410	Northfield Avenue	Opp 9		Sorbus aucuparia	TR: Falling - Significant lateral rooting at surface - cannot surface adequately	01/07/2016	None	12	7	58.33%	7	100.00%	58.33%	Trees which are healthy	The tree outside number 9 is in good condition. We advise that there is no arboricultural need to remove this tree. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of this tree. We believe engineering solutions, including 1, 2 and 7, would enable this tree to be retained. We therefore advise the Council to consider this.	Recommend that a root excavation exercise takes place on this or similar trees to allow further assessment of the practicability of the ITP advice	Tree excavation trials have shown that root removal is not practicable.	SCC - Environmental Maintenance Technical Officer	N/A	N/A	A 1998 Sheffield based study and investigation by Nicoll and Armstrong published in the International Journal of Urban Forestry shows this advice around root handling to be impossible to implement.	Continue with tree replacement as planned.	ITP, SCC and Amey in agreement.	SCC - Environmental Maintenance Technical Officer	Replace tree as planned	Results of excavation trials	Simon Green	Executive Director (P/As)		03/02/2017	N/A		
1201428	Opp 12			Platanus x hispanica	Kerbs missing, cannot install - completely unable to root points, work needed/replacement in carriageway									Tree which is not present	The tree opposite number 12 is not present, and appears to have been previously removed.	Unauthorized removal	Investigation has shown this to be an unauthorised removal by Streets Ahead	SCC - Environmental Maintenance Engineer	Amey to raise reporting job	N/A	N/A	This tree has already been removed	Raise report job due to unauthorised removal	SCC - Environmental Maintenance Technical Officer	Replace tree	Tree removed without Authorisation by unknown third party	Simon Green	Executive Director (P/As)		03/02/2017	N/A		
1202347	Opp 6			Platanus x hispanica	F/W shafted and kerbs damaged by roots - likely to be damaged upon reconstruction									Trees which are healthy	The remaining trees are in good condition and have good life expectancy. We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The tree outside number 6 is causing significant damage to the pavement and kerbs. We believe engineering solutions, including 1, 2 and 7, would enable this tree to be retained. We therefore advise the Council to consider this.	None Required	Replace tree as planned	SCC - Environmental Maintenance Engineer	N/A	N/A	N/A	Continue with tree replacement as planned.	ITP, SCC and Amey in agreement.	SCC - Environmental Maintenance Engineer	Replace tree as planned	All advice considered	Simon Green	Executive Director (P/As)		03/02/2017	N/A		
1202353	Opp 11			Platanus x hispanica	Extensive f/w damage, growing within c/w - no herbaceous									Trees which are healthy	The remaining trees are in good condition and have good life expectancy. We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The tree outside number 11 is causing damage to the pavement and kerbs, and is also leaning into the carriageway. We advise that root cutting considerations justify the removal and replacement of this tree. The remaining trees are in good condition and have good life expectancy. We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees.	None Required	Replace tree as planned	SCC - Environmental Maintenance Engineer	N/A	N/A	N/A	Continue with tree replacement as planned.	ITP, SCC and Amey in agreement.	SCC - Environmental Maintenance Engineer	Replace tree as planned	All advice considered	Simon Green	Executive Director (P/As)		03/02/2017	N/A		
1202364	Opp 46-48			Platanus x hispanica	Extensive f/w damage, growing within c/w - no herbaceous									Trees which are healthy	The remaining trees are in good condition and have good life expectancy. We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The tree outside number 46-48 is causing significant damage to the kerbs, and probably to an adjacent garage gully. We advise that the extent of this damage justifies the removal and replacement of this tree.	None Required	Replace tree as planned	SCC - Environmental Maintenance Engineer	N/A	N/A	N/A	Continue with tree replacement as planned.	ITP, SCC and Amey in agreement.	SCC - Environmental Maintenance Engineer	Replace tree as planned	All advice considered	Simon Green	Executive Director (P/As)		03/02/2017	N/A		
1202351	Opp 5			Platanus x hispanica	Kerbs absent, unable to install/repair without severe root damage									Trees which are healthy	The remaining trees are in good condition and have good life expectancy. We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The tree outside numbers 5, 11, 24, 26, 50 and 52a are causing some damage to the pavement and kerbs. We believe engineering solutions, including 1, 2, 7 and 12, justifying the excavation and re-profiling of the footway, root pruning, use of thinner profile kerbs and making good tree pits where these are present. We advise the Council to consider these options.	Assess site to verify we agree with options given.	Excavation work to date has considered specific points, largely around kerbs line. We now want to carry out a formal study into the ability of excavation beneath the roots of a live highway tree and root handling as previous academic studies in Sheffield have shown this to not be a viable means of retaining highway trees.	SCC - Environmental Technical Officer	N/A	N/A	A 1998 Sheffield based study and investigation by Nicoll and Armstrong published in the International Journal of Urban Forestry shows this advice around root handling to be impossible to implement.	Continue with tree replacement as planned.	ITP, SCC and Amey in agreement.	SCC - Environmental Technical Officer	Replace tree as planned	All advice considered	Simon Green	Executive Director (P/As)		03/02/2017	N/A		
1202349	Swaindale Road	Opp 24	9	Platanus x hispanica	Kerbs absent, unable to install/repair without severe root damage	24/06/16 and 11/07/16	None	43	25	59.68%	13	52.00%	20.63%	Trees which are healthy	The remaining trees are in good condition and have good life expectancy. We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The tree outside numbers 5, 11, 24, 26, 50 and 52a are causing some damage to the pavement and kerbs. We believe engineering solutions, including 1, 2, 7 and 12, justifying the excavation and re-profiling of the footway, root pruning, use of thinner profile kerbs and making good tree pits where these are present. We advise the Council to consider these options.	Assess site to verify we agree with options given.	Excavation work to date has considered specific points, largely around kerbs line. We now want to carry out a formal study into the ability of excavation beneath the roots of a live highway tree and root handling as previous academic studies in Sheffield have shown this to not be a viable means of retaining highway trees.	SCC - Environmental Technical Officer	N/A	N/A	A 1998 Sheffield based study and investigation by Nicoll and Armstrong published in the International Journal of Urban Forestry shows this advice around root handling to be impossible to implement.	Continue with tree replacement as planned.	ITP, SCC and Amey in agreement.	SCC - Environmental Technical Officer	Replace tree as planned	All advice considered	Simon Green	Executive Director (P/As)		03/02/2017	N/A		
1202355	Opp 29			Platanus x hispanica	Extensive f/w damage, growing within c/w - no herbaceous									Trees which are healthy	The remaining trees are in good condition and have good life expectancy. We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The tree outside numbers 5, 11, 24, 26, 50 and 52a are causing some damage to the pavement and kerbs. We believe engineering solutions, including 1, 2, 7 and 12, justifying the excavation and re-profiling of the footway, root pruning, use of thinner profile kerbs and making good tree pits where these are present. We advise the Council to consider these options.	Assess site to verify we agree with options given.	Excavation work to date has considered specific points, largely around kerbs line. We now want to carry out a formal study into the ability of excavation beneath the roots of a live highway tree and root handling as previous academic studies in Sheffield have shown this to not be a viable means of retaining highway trees.	SCC - Environmental Technical Officer	N/A	N/A	A 1998 Sheffield based study and investigation by Nicoll and Armstrong published in the International Journal of Urban Forestry shows this advice around root handling to be impossible to implement.	Continue with tree replacement as planned.	ITP, SCC and Amey in agreement.	SCC - Environmental Technical Officer	Replace tree as planned	All advice considered	Simon Green	Executive Director (P/As)		03/02/2017	N/A		
1202359	Opp 50			Platanus x hispanica	Extensive f/w damage, growing within c/w - no herbaceous									Trees which are healthy	The remaining trees are in good condition and have good life expectancy. We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The tree outside numbers 5, 11, 24, 26, 50 and 52a are causing some damage to the pavement and kerbs. We believe engineering solutions, including 1, 2, 7 and 12, justifying the excavation and re-profiling of the footway, root pruning, use of thinner profile kerbs and making good tree pits where these are present. We advise the Council to consider these options.	Assess site to verify we agree with options given.	Excavation work to date has considered specific points, largely around kerbs line. We now want to carry out a formal study into the ability of excavation beneath the roots of a live highway tree and root handling as previous academic studies in Sheffield have shown this to not be a viable means of retaining highway trees.	SCC - Environmental Technical Officer	N/A	N/A	A 1998 Sheffield based study and investigation by Nicoll and Armstrong published in the International Journal of Urban Forestry shows this advice around root handling to be impossible to implement.	Continue with tree replacement as planned.	ITP, SCC and Amey in agreement.	SCC - Environmental Technical Officer	Replace tree as planned	All advice considered	Simon Green	Executive Director (P/As)		03/02/2017	N/A		
1202357	Opp 52a			Platanus x hispanica	Extensive f/w damage, growing within c/w - no herbaceous									Trees which are healthy	The remaining trees are in good condition and have good life expectancy. We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The tree outside numbers 5, 11, 24, 26, 50 and 52a are causing some damage to the pavement and kerbs. We believe engineering solutions, including 1, 2, 7 and 12, justifying the excavation and re-profiling of the footway, root pruning, use of thinner profile kerbs and making good tree pits where these are present. We advise the Council to consider these options.	Assess site to verify we agree with options given.	Excavation work to date has considered specific points, largely around kerbs line. We now want to carry out a formal study into the ability of excavation beneath the roots of a live highway tree and root handling as previous academic studies in Sheffield have shown this to not be a viable means of retaining highway trees.	SCC - Environmental Technical Officer	N/A	N/A	A 1998 Sheffield based study and investigation by Nicoll and Armstrong published in the International Journal of Urban Forestry shows this advice around root handling to be impossible to implement.	Continue with tree replacement as planned.	ITP, SCC and Amey in agreement.	SCC - Environmental Technical Officer	Replace tree as planned	All advice considered	Simon Green	Executive Director (P/As)		03/02/2017	N/A		

Reference Number	Date	Location	Species	Condition	Assessment	Recommendations	Professional	Notes	Other	Completion Date	Status	Responsible	Role					
1202301	0/5/17	Stouan Road	Padus x fagopyria	Kerfs absent, completely unable to support vertical, unacceptable root damage	The tree shows signs of poor condition and has reasonable life. We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The tree outside number 17 is causing some disruption to the footway and displacement of kerb stones. We consider that engineering solutions 1, 2 and 3 would enable these problems to be resolved. We therefore advise that the Council would be justified in removing and replacing this tree.	Assess site to verify we agree with options given. Request Arney to design if required	SCC Environmental Technical Officer	N/A	N/A	Due to extent of kerb damage a build out of kerb at an estimated cost of £10000 - £2000	Consider build out if funding can be secured	SCC Environmental Technical Officer	Replace tree as planned	After a review of the cost of building engineering solutions to retain trees. The Council does not have such additional funding available and many solutions would also be of a short term nature.	03/02/2017	N/A		
1202302	0/5/29/31	Stouan Road	Acer pseudoplatanus	Kerfs displaced, f/e uplifted, potential 3rd party wall damage	The tree shows signs of poor condition and has reasonable life. We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The tree outside number 20-21 is causing some disruption to the footway and displacement of kerb stones. We consider that engineering solutions 1, 2 and 3 would enable these problems to be resolved. We therefore advise that the Council would be justified in removing and replacing these trees.	None Required	SCC Environmental Technical Officer	N/A	N/A	N/A	Continue with tree replacement as planned.	SCC Environmental Technical Officer	Replace tree as planned	All advice considered	Simon Green	Executive Director (P&A)	03/02/2017	N/A
1201270	0/5/16 and 11/07/16	Side of 43 Archer Lane	Acer pseudoplatanus	Rooting above tarmac along verges, second work mound	The tree shows signs of poor condition and has reasonable life. We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The tree at the side of number 42 Archer Lane has a large root running adjacent to the kerb, with some evidence of pavement repair. We consider that engineering solutions 1, 2 and 3 would enable these problems to be resolved. We therefore advise that the Council would be justified in removing and replacing this tree.	Complete excavations to see extent of roots?	SCC Environmental Technical Officer	N/A	N/A	A 1998 Sheffield based study and investigation by Root and Armstrong published in the International Journal of Urban Forestry shows this advice around root heaving to be impossible to implement. Severe or pruning of roots immediately adjacent to the main stem is not only extremely poor arboricultural practice but would also render this tree structurally unsound in a high wind event, so this is also impossible to implement.	Continue with tree replacement as planned.	SCC Environmental Technical Officer	Replace tree as planned	All advice considered	Simon Green	Executive Director (P&A)	03/02/2017	N/A
N/A	0/5/5	N/A	N/A	N/A	We also noted that the tree outside number 5, which was not referred to us, is causing significant damage to the pavement which presents a serious hazard. We advise the Council to ensure that its plans will resolve this problem.	Investigate if Arney are aware of this issue. Assess site step and look at solutions.	SCC Environmental Technical Officer	N/A	N/A	This tree has been inspected and will be put forward as an additional replacement for the site.	Continue with tree replacement as planned.	SCC Environmental Technical Officer	Replace tree as planned	All advice considered	Simon Green	Executive Director (P&A)	03/02/2017	Arney (Pre-site Technician)
1202310	0/5/12	Canfield Road	Padus x fagopyria	Kerfbases absent - kerbs are adequately repair without tree removal	The tree shows signs of poor condition and has good life expectancy. We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The tree outside number 12 is causing some disruption to the footway and displacement of kerb stones. We consider that engineering solutions 1, 2, 3, 4 and 5 could be deployed to enable the tree to be retained. We therefore advise that the Council should consider carrying out such an investigation if this confirms that the drainage cannot be satisfactorily improved, we advise that the Council would be justified in removing and replacing this tree.	Assess site to verify we agree with options given. Request Arney to design if required	SCC Environmental Technical Officer	N/A	N/A	Root pruning is not advisable due to the detrimental effect it will have on both the tree's structural stability as well as disease susceptibility.	Continue with tree replacement as planned.	SCC Environmental Technical Officer	Replace tree as planned	All advice considered	Simon Green	Executive Director (P&A)	03/02/2017	N/A
1202312	0/5/6	Canfield Road	Padus x fagopyria	Kerfbases absent - kerbs are adequately repair without tree removal	The tree shows signs of poor condition and has good life expectancy. We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The tree outside number 12 is causing some disruption to the footway and displacement of kerb stones. We consider that engineering solutions 1, 2, 3, 4 and 5 could be deployed to enable the tree to be retained. We therefore advise that the Council should consider carrying out such an investigation if this confirms that the drainage cannot be satisfactorily improved, we advise that the Council would be justified in removing and replacing this tree.	Assess site to verify we agree with options given. Request Arney to design if required	SCC Environmental Technical Officer	N/A	N/A	Root pruning is not advisable due to the detrimental effect it will have on both the tree's structural stability as well as disease susceptibility.	Continue with tree replacement as planned.	SCC Environmental Technical Officer	Replace tree as planned	All advice considered	Simon Green	Executive Director (P&A)	03/02/2017	N/A
1202188	0/5/102	Asenath Hippocastanum	Four physiological conditions, Pseudotsuga spraguei pr. Assaut, drainage site to require standard without root damage	The tree is in poor physiological condition, with no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The tree outside number 102 is causing some disruption to the footway and displacement of kerb stones. We consider that engineering solutions 1, 2, 3, 4 and 5 could be deployed to enable the tree to be retained. We therefore advise that the Council should consider carrying out such an investigation if this confirms that the drainage cannot be satisfactorily improved, we advise that the Council would be justified in removing and replacing this tree.	Get an independent inspection into the health of the tree. Before investigating drainage issues.	SCC Client Technical to verify condition and high way engineer to verify drainage works	SCC Environmental Technical Officer	N/A	N/A	This tree is in poor physiological condition, with no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The tree outside number 102 is causing some disruption to the footway and displacement of kerb stones. We consider that engineering solutions 1, 2, 3, 4 and 5 could be deployed to enable the tree to be retained. We therefore advise that the Council should consider carrying out such an investigation if this confirms that the drainage cannot be satisfactorily improved, we advise that the Council would be justified in removing and replacing this tree.	Continue with tree replacement as planned.	SCC Environmental Technical Officer	Replace tree as planned	All advice considered	Simon Green	Executive Director (P&A)	03/02/2017	N/A
1202333	0/5/86	Acer pseudoplatanus	Rotting and lateral roots growing above tarmac, kerbs may be damaged upon reconstruction	We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The tree outside number 86 is causing some disruption to the footway and displacement of kerb stones. We consider that engineering solutions 1, 2 and 3 would enable these problems to be resolved. We therefore advise that the Council would be justified in removing and replacing this tree.	Assess site to verify we agree with options given. Request Arney to design if required	Two excavation trials have shown that root treatment is not practicable.	SCC Environmental Technical Officer	N/A	N/A	Rotting and lateral roots from this tree are getting above the tarmac on the footway. These are too large to be cut, severed or grouted with barriers or root panels.	Continue with tree replacement as planned.	SCC Environmental Technical Officer	Replace tree as planned	Results of excavation trials	Simon Green	Executive Director (P&A)	03/02/2017	N/A
1202335	0/5/78	Acer pseudoplatanus	Rotting roots growing into car - kerbs absent - not to be damaged upon reconstruction	We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The tree outside number 78 has rotten roots in the carriageway and is causing significant damage to the pavement. We do not consider this damage can be resolved without removing the tree. We therefore advise that the Council would be justified in removing and replacing this tree.	None Required	Replace tree as planned	SCC Environmental Technical Officer	N/A	N/A	N/A	Continue with tree replacement as planned.	SCC Environmental Technical Officer	Replace tree as planned	All advice considered	Simon Green	Executive Director (P&A)	03/02/2017	N/A
1202340	0/5/11	James House (Facing junction with Edgemoor Road)	Acer pseudoplatanus	Extensive f/e uplift, unable to work around repair without root damage	We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The tree outside 11 James House (Facing junction with Edgemoor Road) is causing significant uplift of the pavement. We do not consider this damage can be resolved without removing the tree. We therefore advise that the Council would be justified in removing and replacing this tree.	None Required	Replace tree as planned	SCC Environmental Technical Officer	N/A	N/A	Continue with tree replacement as planned.	SCC Environmental Technical Officer	Replace tree as planned	All advice considered	Simon Green	Executive Director (P&A)	03/02/2017	N/A
1202339	0/5/32	Edgemoor Road	Acer pseudoplatanus	Extensive f/e uplift by shallow roots, unable to repair without root damage	We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The remaining trees, those outside numbers 32, 76, Church (2nd tree on road from bottom) and 6 are all causing damage to the pavement and in some instances displacement of kerbs. We consider that engineering solutions 1, 2, 3, 4 and 5 could be used to enable these trees to be retained. We advise the Council to consider this.	Complete excavations to see extent of roots?	SCC Environmental Technical Officer	N/A	N/A	A 1998 Sheffield based study and investigation by Root and Armstrong published in the International Journal of Urban Forestry shows this advice around root heaving to be impossible to implement. Severe or pruning of roots immediately adjacent to the main stem is not only extremely poor arboricultural practice but would also render this tree structurally unsound in a high wind event, so this is also impossible to implement.	Continue with tree replacement as planned.	SCC Environmental Technical Officer	Replace tree as planned	Results of excavation trials	Simon Green	Executive Director (P&A)	03/02/2017	N/A
1202337	0/5/70	Acer pseudoplatanus	Extensive f/e uplift by shallow roots, unable to repair without root damage	We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The remaining trees, those outside numbers 32, 76, Church (2nd tree on road from bottom) and 6 are all causing damage to the pavement and in some instances displacement of kerbs. We consider that engineering solutions 1, 2, 3, 4 and 5 could be used to enable these trees to be retained. We advise the Council to consider this.	Complete excavations to see extent of roots?	Two excavation trials have shown that root treatment is not practicable.	SCC Environmental Technical Officer	N/A	N/A	A 1998 Sheffield based study and investigation by Root and Armstrong published in the International Journal of Urban Forestry shows this advice around root heaving to be impossible to implement. Severe or pruning of roots immediately adjacent to the main stem is not only extremely poor arboricultural practice but would also render this tree structurally unsound in a high wind event, so this is also impossible to implement.	Continue with tree replacement as planned.	SCC Environmental Technical Officer	Replace tree as planned	Results of excavation trials	Simon Green	Executive Director (P&A)	03/02/2017	N/A
1202304	0/5/10	St. Paul's Church (2nd tree on road from bottom)	Acer pseudoplatanus	Kerfs displaced - unable to repair without root damage	We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The remaining trees, those outside numbers 32, 76, Church (2nd tree on road from bottom) and 6 are all causing damage to the pavement and in some instances displacement of kerbs. We consider that engineering solutions 1, 2, 3, 4 and 5 could be used to enable these trees to be retained. We advise the Council to consider this.	Complete excavations to see extent of roots?	Two excavation trials have shown that root treatment is not practicable.	SCC Environmental Technical Officer	N/A	N/A	Continue with tree replacement as planned.	SCC Environmental Technical Officer	Replace tree as planned	Results of excavation trials	Simon Green	Executive Director (P&A)	03/02/2017	N/A
1202304	0/5/6	Acer pseudoplatanus	Extensive f/e uplift and displacement, kerbs displaced by growth of stem immediately behind	We advise that there is no arboricultural need to remove these trees. We have therefore considered whether there are engineering solutions that would prevent the need for removal and replacement of these trees. The remaining trees, those outside numbers 32, 76, Church (2nd tree on road from bottom) and 6 are all causing damage to the pavement and in some instances displacement of kerbs. We consider that engineering solutions 1, 2, 3, 4 and 5 could be used to enable these trees to be retained. We advise the Council to consider this.	Complete excavations to see extent of roots?	Two excavation trials have shown that root treatment is not practicable.	SCC Environmental Technical Officer	N/A	N/A	A 1998 Sheffield based study and investigation by Root and Armstrong published in the International Journal of Urban Forestry shows this advice around root heaving to be impossible to implement. Severe or pruning of roots immediately adjacent to the main stem is not only extremely poor arboricultural practice but would also render this tree structurally unsound in a high wind event, so this is also impossible to implement.	Continue with tree replacement as planned.	SCC Environmental Technical Officer	Replace tree as planned	Results of excavation trials	Simon Green	Executive Director (P&A)	03/02/2017	N/A

