

Independent Tree Panel for Sheffield

Paul Billington
Director of Culture
Sheffield City Council

By email

31 March 2017

Dear Paul

Milden Road

The Independent Tree Panel has reviewed Sheffield City Council's plans for the removal and replacement of trees on this street. The summary data for the street are:

Number of trees	35
Number of trees referred to ITP	15
% of trees referred to ITP	42.9%
Number of households	59
Number of households responding to survey	24
Number of households responding to the survey who objected to the proposals	12


Andy Bagshaw, David Graham and I inspected the trees on 23 February 2017.

We have considered the structural and physiological condition of each tree, and hence whether to advise the Council to consider removing and replacing the tree for this reason. Please note that in the absence of a comment to the contrary, we found the tree to be healthy and not in need of replacement for an arboricultural reason.

We considered whether the engineering solutions provided for in the Streets Ahead programme could be deployed to enable each tree to be retained, and hence whether to advise the Council to consider deploying one or more solutions for this purpose. We took account of the information provided by the Council about the engineering solutions.

We have summarised our comments and advice in the attached table.

Yours sincerely



Andy Buck
Chair

Copy:
James Henderson
Independent Tree Panel members

Milden Road			
Fell Job No	Tree Location	Comment	Advice
12026806	o/s 67	3 rd party damage. Kerb displaced. Buttress root in footway.	Remove and replace tree.
12026814	o/s 60-62	Kerb displaced. Footway lifted twice. Water ponding.	Remove and replace tree.
12026841	o/s 4	Kerb absent.	Repair tarmac.
12026824	o/s 49	Kerb absent – significant.	Remove and replace tree.
12026802	o/s 61	Kerb displaced.	Half width kerb.
12026834	o/s 14-16	3 rd party damage. Kerb displaced. Footway damaged.	Remove and replace tree.
12026812	o/s 64	3 rd party damage. Footway damaged. Utility cover adjacent.	Remove and replace tree.
12026828	o/s 54	Footway damaged. Driveway damaged	Remove and replace tree.
12026818	Adj-side of 50 Vainor road.	Kerb displaced.	Half width kerb.
12026831	o/s 30-32	Kerb displaced. Footway damaged. Adjacent gully.	Remove and replace tree.
12026821	Opp 2	Kerb displaced. Footway damaged and lifted.	Remove and replace tree.
12026837	o/s 6	Kerb satisfactory. Footway damaged.	Remove and replace tree.
12026810	adj 99a Langsett ave	Kerb displaced. Footway damaged. Adjacent utility box.	Remove and replace tree.
12026844	Adj 40 Vainor road, (bottomside of 2 Milden rd)	Kerb displaced. Root in carriageway.	Remove kerb. Consider root prune. Half width kerb.
12026808	adj 99 Langsett ave	Kerb displaced – significant.	Remove and replace tree.