

Independent Tree Panel for Sheffield

Paul Billington
Director of Culture
Sheffield City Council

By email

31 March 2017

Dear Paul

Stanley Road

The Independent Tree Panel has reviewed Sheffield City Council's plans for the removal and replacement of trees on this street. The summary data for the street are:

Number of trees	14
Number of trees referred to ITP	6
% of trees referred to ITP	42.9%
Number of households	21
Number of households responding to survey	11
Number of households responding to the survey who objected to the proposals	6


Andy Bagshaw, David Graham and I inspected the trees on 9 February 2017.

We have considered the structural and physiological condition of each tree, and hence whether to advise the Council to consider removing and replacing the tree for this reason. Please note that in the absence of a comment to the contrary, we found the tree to be healthy and not in need of replacement for an arboricultural reason.

We considered whether the engineering solutions provided for in the Streets Ahead programme could be deployed to enable each tree to be retained, and hence whether to advise the Council to consider deploying one or more solutions for this purpose. We took account of the information provided by the Council about the engineering solutions.

We have summarised our comments and advice in the attached table.

Yours sincerely



Andy Buck
Chair

Copy:
James Henderson
Independent Tree Panel members

Stanley Road			
Fell Job No	Tree Location	Comment	Advice
12016286	o/s 14/16	Kerb displaced. Carriageway damaged.	Remove and replace tree.
12024577	o/s 22	Kerb displaced. Adjacent gully.	Remove and replace tree.
12024579	o/s 15, (opp 24)	Footway obstructed (75cm).	Remove and replace tree.
12024581	between 11-15	Kerb displaced. Footway ramped.	Remove and replace tree.
12024583	Side of 22 Meersbrook Rd, at bottom Stanley Rd (o/s green wooden gates)	Kerb displaced. Footway ramped. Adjacent drive ramped.	Remove and replace tree.
12016288	facing 37 meersbrook road (bottom of Stanley Rd)	Kerb displaced. Footway heaved.	Remove and replace tree.
12016288	facing 37 meersbrook road (bottom of Stanley Rd)	Kerb displaced. Footway damaged. Carriageway damaged.	Remove and replace tree.