

Independent Tree Panel for Sheffield

Paul Billington
Director of Culture
Sheffield City Council

By email

31 March 2017

Dear Paul

Marlcliffe Road

The Independent Tree Panel has reviewed Sheffield City Council's plans for the removal and replacement of trees on this street. The summary data for the street are:

Number of trees	17
Number of trees referred to ITP	5
% of trees referred to ITP	29.4%
Number of households	139
Number of households responding to survey	31
Number of households responding to the survey who objected to the proposals	17


Andy Bagshaw, David Graham and I inspected the trees on 10 February 2017.

We have considered the structural and physiological condition of each tree, and hence whether to advise the Council to consider removing and replacing the tree for this reason. Please note that in the absence of a comment to the contrary, we found the tree to be healthy and not in need of replacement for an arboricultural reason.

We considered whether the engineering solutions provided for in the Streets Ahead programme could be deployed to enable each tree to be retained, and hence whether to advise the Council to consider deploying one or more solutions for this purpose. We took account of the information provided by the Council about the engineering solutions.

We have summarised our comments and advice in the attached table.

Yours sincerely



Andy Buck
Chair

Copy:
James Henderson
Independent Tree Panel members

Marlcliffe Road			
Fell Job No	Tree Location	Comment	Advice
12026865	o/s 191	Kerb displaced. Footway heaved – significant.	Remove and replace tree.
12026857	o/s 19, flat 1	Kerb displaced. Footway damaged.	Tree pit. Root prune.
12026861	o/s 61	Kerb displaced. Basal ganoderma – normal vitality.	Extend tree pit. Root prune.
12026854	OPP 16	Kerb displaced. Footway lifted.	Half width or dropped kerb. Tree pit.
12013850	o/s 82	Tree in satisfactory condition.	No action needed. Retain tree.